IN THE DRAWINGS:

Please amend FIG. 3B in accordance with the replacement sheet attached hereto.

Replacement Sheet

QP1_Next_VA_REG	
QP1_HW_Doorbell_REG	
QP1_In_Service_Bit	
QP2_Next_VA_REG	
QP2_HW_Doorbell_REG	
QP2_In_Service_Bit	o o
	0
QPx_Next_VA_REG	
QPx_HW_Doorbell_REG	
QPx_In_Service_Bit	
Hardware Adapter <u>175</u>	

FIG. 3A

Virtual Address	Work Queue Element Information	Next Virtual Address	Next WQE Posted	Busy <u>310</u>
WQE_VA0		0	0	0
WQE_VA1		0	0	0
WQE_VA2		0	0	0
WQE_VA3		0	0	0
QPx Driver Last WQE Accessed Register 215		QPx 210		

FIG. 3B